## National Transportation Safety Board Washington, DC 20594

## **Brief of Accident**

## Adopted 08/05/1993

DCA9	1MA021
------	--------

Airplane

INFORMATION IN THE APPROVED AIRPLANE FLIGHT MANUAL.

File No. 153		)2/17/1991	CLEVELAND, OH	Aircraft Reg No. N565PC			Time (Local): 00:19 EST		
Engine Airc Numbe Operating ( Nan Type of Flig	Make/Model: rraft Damage: er of Engines: Certificate(s): me of Carrier: ht Operation:		IRLINES	Crew Pass	Fatal 2 0	Serious 0 0	Minor/None 0 0		
Last Depart. Point: Destination: Airport Proximity: Airport Name: Runway Identification: Runway Length/Width (Ft): Runway Surface: Runway Surface Condition:  Same as Accident/Incident Location INDIANAPOLIS , IN On Airport CLEVELAND-HOPKINS INT'L 23L 8998 / 150 Asphalt Wet		Condition of Light: Night/Dark Weather Info Src: Weather Observation Facility Basic Weather: Instrument Conditions Lowest Ceiling: 1500 Ft. AGL, Obscured Visibility: 1.00 SM Wind Dir/Speed: 220 / 014 Kts Temperature (°C): -5 Precip/Obscuration: Snow / None							
Pilot-in-Command	Age:	46			Flight Ti	me (Hours)			
Certificate(s)/Rating(s) Airline Transport; Multi-engine Land; Single-engine Land; Instrument Ratings				Total All Aircraft: 10505 Last 90 Days: Unk/Nr Total Make/Model: 505					

THE FLIGHT HAD FLOWN THROUGH WEATHER CONDUCIVE TO AIRFRAME ICE ABOUT 40 MIN PRIOR TO THE ACCIDENT DURING DESCENT INTO CLEVELAND. DURING THE 35-MINUTE TURNAROUND AT CLEVELAND THE CREW DID NOT EXIT THE AIRPLANE TO CONDUCT AN EXTERIOR PREFLIGHT INSPECTION TO VERIFY THAT THE WINGS WERE FREE OF ICE CONTAMINATION. IT WAS SNOWING WHILE THEY WERE ON THE GROUND. THE AIRPLANE STALLED AND ROLLED INTO THE GROUND IMMEDIATELY AFTER TAKEOFF. THERE WAS NO OPERATOR REQUIREMENT FOR THE PREFLIGHT. THE FLIGHT HAD NOT BEEN GIVEN TRAINING REGARDING THE EFFECTS OF WING CONTAMINATION ON THE AIRPLANE. THE FAA AND THE MANUFACTURER HAVE BEEN AWARE FOR SEVERAL YEARS OF THE PROPENSITY OF THE DC-9 SERIES 10 TO THE LOSS OF CONTROL CAUSED BY WING CONTAMINATION, BUT NEITHER OF THEM TOOK POSITIVE ACTION TO INCLUDE RELATED

Total Instrument Time: UnK/Nr

DCA91MA021

File No. 153 02/17/1991 CLEVELAND, OH Aircraft Reg No. N565PC Time (Local): 00:19 EST

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: TAKEOFF - INITIAL CLIMB

## **Findings**

- 1. (F) WEATHER CONDITION SNOW
- 2. (C) WING ICE
- 3. (C) AIRCRAFT PREFLIGHT NOT PERFORMED PILOT IN COMMAND
- 4. (C) ICE/FROST REMOVAL FROM AIRCRAFT NOT PERFORMED PILOT IN COMMAND
- (C) INADEQUATE TRAINING COMPANY/OPERATOR MANAGEMENT
- 6. (C) ACFT/EQUIP, INADEQUATE AIRCRAFT MANUALS MANUFACTURER
- 7. (C) ACFT/EQUIP,INADEQUATE AIRCRAFT MANUALS FAA(OTHER/ORGANIZATION)
- 8. STALL INADVERTENT PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

THE FAILURE OF THE FLIGHTCREW TO DETECT AND REMOVE ICE CONTAMINATION ON THE AIRPLANE'S WINGS, WHICH WAS LARGELY A RESULT OF A LACK OF APPROPRIATE RESPONSE BY THE FEDERAL AVIATION ADMINISTRATION, DOUGLAS AIRCRAFT COMPANY, AND RYAN INTERNATIONAL AIRLINES TO THE KNOWN CRITICAL EFFECT THAT A MINUTE AMOUNT OF CONTAMINATION HAS ON THE STALL CHARACTERISTICS OF THE DC-9 SERIES 10 AIRPLANE. THE ICE CONTAMINATION LED TO WING STALL AND LOSS OF CONTROL DURING THE ATTEMPTED TAKEOFF. (NTSB REPORT AAR-91/09)